Licensee: AUSSIE SKIPS RECYCLING PTY LTD
Address: PO Box 156, Belfield, NSW, 2191
Premises: 13 Bellfrog St, Greenacre, 2190

## Monthly water sampling (EPL Point 4 - pit receiving drainage from vegetated filter basin, NE corner of site)

| Sampling Date | Date data obtained | Date data published on website | pH | Total Suspended Solids (mg/L) | Comments/justification | EPL limits | | Sample compliant with EPL limits? | |
|---|---|---|---|---|---|---|---|---|---|
| | | | | | | pH | TSS (mg/L) | pH | TSS |
| 27/03/2020 | 2/05/2020 | Unknown | 7.8 | 350 | NA | 6.5-8.5 | 50 | YES | NO |
| 29/04/2020 | 5/05/2020 | 19/05/2020 | 8.1 | 14 | NA | 6.5-8.5 | 50 | YES | YES |
| 29/05/2020 | 10/06/2020 | Unknown | 6.7 | 1 | NA | 6.5-8.5 | 50 | YES | YES |
| 30/06/2020 | NA | Unknown | NA | NA | Discharge point dry during all inspections | 6.5-8.5 | 50 | NA | NA |
| 14/07/2020 | 17/07/2020 | Unknown | 7.4 | 200 | Discharge after heavy rainfall conditions | 6.5-8.5 | 50 | YES | NO |
| 17/07/2020 | 17/08/2020 | Unknown | NA | 76 | Normal conditions. pH not analysed as sample submitted outside of holding time. | 6.5-8.5 | 50 | NA | NO |
| 10/08/2020 | 14/08/2020 | 28/08/2020 | 7.8 | 50 | Approx. 15 mm rain in preceding days. Swale moist. No odour. Water running. | 6.5-8.5 | 50 | YES | YES |
| 24/09/2020 | 30/09/2020 | 9/09/2020 | 7.4 | 26 | Water running from site activities, swale soggy and full of water. | 6.5-8.5 | 50 | YES | YES |
| 28/10/2020 | NA | NA | NA | NA | No water running, despite high rainfall in preceding days. No sample taken. | 6.5-8.5 | 50 | NA | NA |
| 30/11/2020 | 2/12/2020 | 17/12/2020 | 7.5 | 19 | NA | 6.5-8.5 | 50 | YES | YES |
| 22/12/2020 | 22/12/2020 | NA | NA | NA | No water running. Sample not taken. | 6.5-8.5 | 50 | NA | NA |
| 21/01/2021 | NA | NA | NA | NA | No water running, despite high rainfall in preceding days. No sample taken. | 6.5-8.5 | 50 | NA | NA |
| 22/02/2021 | 26/02/2021 | 28/04/2021 | 6.78 | 20 | Rain in preceeding period | 6.5-8.5 | 50 | YES | YES |
| 29/03/2021 | NA | 28/04/2021 | NA | NA | No water running, despite high rainfall in preceding days. No sample taken. | 6.5-8.5 | 50 | NA | NA |
| 21/04/2021 | NA | 28/04/2021 | NA | NA | No water running. Sample not taken. Tanks being installed in discharge channel. | 6.5-8.5 | 50 | NA | NA |
| 27/05/2021 | NA | 4/06/2021 | NA | NA | No water running. Sample not taken. Tanks in discharge channel. | 6.5-8.5 | 50 | NA | NA |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

N
0 20 40 80
Metres

4Pillars ENVIRONMENTAL CONSULTING

Date Produced: 31/03/2020
Basemap Imagery: NSW Globe, © Department Finance, Services & Innovation [07/04/2018]
(Used under Creative Commons https://creativecommons.org/licenses/by/3.0/au/legalcode)